Monthly Operational

Site 5905	Willand	=	23/08/23
	Gables Lea	(date/time) by	0-30-MW
Equipment	Inspected	Defect	Risk Low Med High Imm
Fence			
Gate Pedestrian x 2			
Goals 2 sets			
Litter Bin Topsy			
Miscellaneous Items			
Multi Play Unit			
Roundabout			
Safety Surface			
Seat Stnd Plastic			
Sign Standard	└		

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

Monthly Operational

Site 5920	Willand	Inspected on	23/08/23
	Gables Lea (Parish Equipment)	(date/time) by	10-10-MW
Equipment Basket Ball	Inspected	Defect	Risk Low Med High Imm
BMX Track	WEW KRACK UN	JOEN CONSTRUCTION	
Climbing Frame Metal		· · · · · · · · · · · · · · · · · · ·	
Miscellaneous Items			
Picnic Bench			
Safety Surface			
See Saw	U		
Spring Mobile Elephant			
Spring Mobile Horse			
Swing Double Cradle			
Swing Double Flat			
Swing Four Flat	<u> </u>		
Tarmac Surface	₫		

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

Teen Shelter	
Trim Trail	

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

Pla	ay Areas - 3	Sites due for Inspection M	onthly Operational
Site 6503	Mobile Mobile 03	Inspected on (date/time) by	23/08/23 10-00-MU
Equipment	Inspected	Defect	Risk Low Med High Imm
Launch Ramp	V		
Miscellaneous Items			
Sign In Line Skating Safe	ety 🔽		

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

	Play A	Areas -	Sites due for Inspection	Mo	nthly C	perational
Site 65		lland bile 01		cted on time) by	23 08	5 MG
Equipment	Insp	pected	Defect		Low M	Risk led High Imm
Fun Box		i l	,			
Miscellaneous It	ems					
Sign In Line Ska	iting Safety			5		

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

PI	lay Areas - S	Sites due for Inspection Mo	nthly Operational
Site 6502	Mobile Mobile 02	Inspected on (date/time) by	2813 08 23 09-50-MU
Equipment	Inspected	Defect	Risk Low Med High Imm
Grinding Box			
Miscellaneous Items			
Sign In Line Skating Sa	afety		

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

Monthly Operational

Site 5906	Willand	Inspected on	23 08 23
	Chestnut Drive	(date/time) by	10-55-MW
Equipment	Inspected	Defect	Risk Low Med High Imm
Fence	IX.	RUBBER STOPPER MISSING FROM	
Gate Pedestrian x 2		SLAM PLATE,	
Litter Bin Guppy			
Miscellaneous Items			
Multi Play Unit Senior			
Safety Surface			
Seat Other Plastic			
Sign No Ball Games			
Sign Standard			
Swing Double Cradle			
Swing Double Flat			
Description Restat	TH		口口口口口

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

Monthly Operational

Site 5902	Willand The Orchards	Inspected on (date/time) by	23/08/23 09-30-MV
Equipment	Inspected	Defect	Risk Low Med High Imm
Climbing Frame Ladder			
Dynamo Amazon Basin			
Fence			
Gate Pedestrian x 2			
Gate vehicular			
Goals 1 Set			
Litter Bin Topsy			
Miscellaneous Items			
Picnic Table Plastic			
Safety Surface			
See Saw Gull Wing			
Sign Standard x 2			
Swing Double Flat	<u> </u>		

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

Monthly Operational

Site 5908	Willand	Inspected on	23 68 23
	Worcester Crescent	(date/time) by	8.50 MW
Equipment Bench Plastic	Inspected	Defect	Risk Low Med High Imm
Fence			
Gate pedestrian		į.	
Gate vehicular			
Litter Bin			
Miscellaneous Items	Manhana	BOTTOM METAL STEP STATTIN	
Multi Play Unit /Slide	Lust	ISON ON PRINCE STREET STATES	
Safety Surface			
See Saw			
Sign No Ball Games			
Sign Standard			
Swing Double Cradle	6		

Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

Play Areas - Sites due for Inspection **Monthly Operational** 23/08 Site 5909 Willand Inspected on Mallow Court (date/time) by 08-Risk Defect **Equipment** Inspected Med High Imm Bench Plastic x2 Fence Gate Pedestrian x 2 Gate vehicular Litter Bin Topsy Miscellaneous Items Multi Play Unit /Slide Safety Surface Sign Standard Spring Mobile Horse

Please note

Swing Double Cradle

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

F	Play Areas - Sit	es due for Inspection	Monthly Operational
Site 5901	Willand South View		time) by 10-46-60
Equipment	Inspected	Defect	Risk Low Med High Imm
Fence Bow Top			
Gate Pedestrian x1			
Litter Bin Guppy	QJEA.H	WINGING TREE BRANCHES V	Như ch
Miscellaneous Items		XHO CUMING Back	
Multi Play Unit /Slide			
Safety Surface		·	
Sign Standard			
Spring Mobile Cat			
Spring Mobile Dog			
Swing Double Cradle			

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay