**Monthly Operational** 

<b>Site</b> 5906	Willand Chestnut Drive	Inspected of (date/time)	.0100123
Equipment	Inspected	Defect	<b>Risk</b> Low Med High Imm
Fence			
Gate Pedestrian x 2			
Litter Bin Guppy			
Miscellaneous Items		- Xen	
Multi Play Unit Senior			
Safety Surface		Or Saken.	
Seat Other Plastic		4 4 · ·	
Sign No Ball Games			
Sign Standard			
Swing Double Cradle			
Swing Double Flat			

#### Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 Addison Contact - Mike Watts 07967179676

	Play Areas - S	ites due for Inspection	Monthly Operational
<b>Site</b> 5901	Willand South View	Inspected (date/time	2 100 20
Equipment	Inspected	Defect	<b>Risk</b> Low Med High Imm
Fence Bow Top			
Gate Pedestrian x1			
Litter Bin Guppy			
Miscellaneous Items			
Multi Play Unit /Slide		· · · · · · · · · · · · · · · · · · ·	
Safety Surface	V		
Sign Standard			
Spring Mobile Cat			
Spring Mobile Dog			
Swing Double Cradle			

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 Addian Contact - Mike Watts 07967179681

**Monthly Operational** 

<b>Site</b> 5909	Willand	Inspected on	12/06/23.
	Mallow Court	(date/time) by	09-30. MU
Equipment	Inspected	Defect	Risk Low Med High Imm
Bench Plastic x2			
Fence			
Gate Pedestrian x 2			
Gate vehicular			
Litter Bin Topsy			
Miscellaneous Items			
Multi Play Unit /Slide			
Safety Surface			
Sign Standard			
Spring Mobile Horse			
Swing Double Cradle			

#### Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

Monthly Operational

<b>Site</b> 5908	Willand	Inspected on	12 06 23.
	Worcester Crescent	(date/time) by	09.50-MW
Equipment	Inspected	Defect	<b>Risk</b> Low Med High Imm
Bench Plastic			
Fence			
Gate pedestrian			
Gate vehicular	Bin full.		
Litter Bin			
Miscellaneous Items			
Multi Play Unit /Slide			
Safety Surface			
See Saw			
Sign No Ball Games			
Sign Standard			
Swing Double Cradle	Ø		

#### Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

For urgent repairs Contact - Mike Watts 07967179681 Addition Contact - Mike Watts 07967179681

**Monthly Operational** 

<b>Site</b> 5902	Willand The Orchards	Inspected on (date/time) by	12/06/23.
Equipment	Inspected	Defect	Risk Low Med High Imm
Climbing Frame Ladder			
Dynamo Amazon Basin			
Fence			
Gate Pedestrian x 2			
Gate vehicular			
Goals 1 Set			
Litter Bin Topsy			
Miscellaneous Items			
Safety Surface			
See Saw Gull Wing			
Sign Standard x 2			
Swing Double Flat			

#### Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

**Monthly Operational** 

<b>Site</b> 5920	Willand	Inspected on	12/06/23.
	Gables Lea (Parish Equipment	(date/time) by	11-30-m
<b>Equipment</b> Basket Ball	Inspected  MONTOR POPTING  AROND THE H	Defect LWOODEN BackBoard 400 P.	Risk Low Med High Imm
BMX Track			
Climbing Frame Metal			
Miscellaneous Items			
Picnic Bench			
Safety Surface			
See Saw			
Spring Mobile Elephant			
Spring Mobile Horse			
Swing Double Cradle			
Swing Double Flat			
Swing Four Flat			
Tarmac Surface			

## Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

Teen Shelter	
Trim Trail	

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

**Monthly Operational** 

<b>Site</b> 5905	Willand Gables Lea	Inspected on (date/time) by	12/06/23
Equipment	Inspected	Defect	Risk Low Med High Imm
Fence			
Gate Pedestrian x 2			
Goals 2 sets			
Litter Bin Topsy			
Miscellaneous Items			
Multi Play Unit			
Roundabout	$\mathbb{Z}_{-}$		
Safety Surface	$\not\square$		
Seat Stnd Plastic	Z		
Sign Standard	<u>/</u>		

#### Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

Pla	ay Areas - Si	tes due for inspection Mo	nthly Operational
<b>Site</b> 6502	Mobile Mobile 02	Inspected on (date/time) by	12/06/23
Equipment	Inspected	Defect	<b>Risk</b> Low Med High Imm
Grinding Box			
Miscellaneous Items			
Sign In Line Skating Sat	fet		

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

### Play Areas - Sites due for Inspection Monthly Operational Site 6503 Mobile Inspected on Mobile 03 (date/time) by 12.35-Equipment Inspected Defect Med High Imm Launch Ramp Miscellaneous Items Sign In Line Skating Safet

### Please note

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay

	Play Areas - Sit	es due for inspection ivid	onthly Operational
<b>Site</b> 6501	Willand Mobile 01	Inspected on (date/time) by	12/06/23 12-20-MU
Equipment	Inspected	Defect	<b>Risk</b> Low Med High Imm
Fun Box			
Miscellaneous Items	s		
Sign In Line Skating	Safet		

The painting of equipment is assessed annually and need not form part of the safety inspection.

Defects must be Risk Assessed in the following way. Low = Monitor Medium = action within 3 to 6 months High = action within 1 month and Immediate = action without delay